



Dart Aerospace Ltd.
1270 Aberdeen St
Hawkesbury, ON
K6A 1K7
Canada

Tel (613) 632-5200

Ship May 24
Order 5782
003426

648.4701

Job Sheet 176647



2

Part No: 648.4701

Job Qty: 1 ea

Part Name: C2 Overhaul Kit



Part Weight: 0 lbs

Status: Scheduled

Priority: Medium

Job Created: 4/26/18

Job Tracking No:

Created By: Marie Lajeunesse

Due Date: 5/24/18

Type: SOLD

Description:

Note: DWG OM_OOPM-C2 Rev 4 IPP Rev A 18.03.07 New issue DP Verify DD

Ship Via:

Bill of Materials

Job Routing

Op No	Operation	Qty	Start Date	Due Date	Standard		Workcenter/Supplier		Sign-off
					Setup hrs	Run Hrs	Workcenter / Supplier	Lead Time	
90	Start up Operation	1 Ea		5/24/18	0.00	0.00	Start Up Stores/Pkg-1		18-06-12
110	Small Fab	1 pcs		5/24/18	0.00	1.00	Small Fab-9		18-06-12
120	QC	1 pcs		5/24/18	0.00	0.00	QC4		38
125	DC	1 pcs		5/24/18	0.00	0.00	DC		SRB 9-88 DAS
130	Packaging	1 pcs		5/24/18	0.00	0.00	Packaging3-1		28
140	QC21-FG	1 Ea		5/24/18	0.00	0.00	QC21		DAS 9-88

Part Op 110 - Pick kit

Descriptions: 125 - Photocopy bluefile & type labels per PPP 648.7401

130 - Identify and pack for shipping as per PPP 648.4701

Job BOM

Part / Item	Component Name	Quantity	Operation	Container
188-FPSS-1032-1/4	Set Screw	2 Ea (2 ea)	90-Start up Operation	5058750
600.1310-AP	Label	1 pcs (1 ea)	90-Start up Operation	5029480
600.1314P	C2 Caution Sticker	1 pcs (1 ea)	90-Start up Operation	5029484
AN3-14A	Bolt	1 Ea (1 ea)	90-Start up Operation	5067270
AN4-16A	Bolt	2 Ea (2 ea)	90-Start up Operation	5068654
AN4-17A	Bolt	1 Ea (1 ea)	90-Start up Operation	5070163
AN960-10	Washer	1 Ea (1 ea)	90-Start up Operation	5027138
AN960-10	Washer, #10	4 Ea (4 ea)	90-Start up Operation	5068663
AN960-11	Flat Washer Dia 1/4"	6 Ea (6 ea)	90-Start up Operation	5056461
C2-12-1 P	Lock Bushing	2 Ea (2 ea)	90-Start up Operation	5029234
C2-12-7P	Teflon Spacer Lock	2 pcs (2 ea)	90-Start up Operation	5029236
C2-12-8	DUST SHEILD - C2 HOOK	2 Ea (2 ea)	90-Start up Operation	5075404
C2-13-5	Keeper Spring	1 (1 ea)	90-Start up Operation	5075033
C2-14-2	Label Rivets	4 Ea (4 ea)	90-Start up Operation	5057170
C2-3-1	Bearing DU	2 pcs (2 ea)	90-Start up Operation	5068886
C2-3-2-1	Roller Pin Retaining Ring	2 Ea (2 ea)	90-Start up Operation	5056845
C2-3-3-1	Latch Roller DU Bearing	1 Ea (1 ea)	90-Start up Operation	5050472
C2-3-5	Spacer, Teflon	2 Ea (2 ea)	90-Start up Operation	5058758
C2-3-8	Actuator Bushing	2 Ea (2 ea)	90-Start up Operation	5072543
C2-4-1	Trunnion Bushing	2 (2 ea)	90-Start up Operation	5075145
C2-7-1P	Load Beam Bumper	1 pcs (1 ea)	90-Start up Operation	5029255
C2-7-2 P	Lock Bumper	2 Ea (2 ea)	90-Start up Operation	5029256

DAS
03
9-88

DQA: _____ Date: _____

WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐	AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐			
Date : _____	Step #: _____	QTY Effective : _____		MRB (QSI042) Approval	
Description Work Order Deviation		Disposition		Completed By	
				Lead hand / Supervisor Approval Verification	
				QC / QA Coordinator Approval	
Root Cause		FAULT CATEGORY			
Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐	No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐	Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐	Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐	Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Misabeled ☐ Fit/Function ☐ Misaligned/off center ☐	Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐
OTHER : _____					

C2-9-3	Clock Spring Cover Screw >	4 Ea (4 ea)	90-Start up Operation	5061527
C3-10-2	Lock Spring ~	1 Ea (1 ea)	90-Start up Operation	5070352
C3-3-4-1	Ring, Retaining ~	4 pcs (4 ea)	90-Start up Operation	5070542
C3-3-9 P	Actuator Spring ~	1 pcs (1 ea)	90-Start up Operation	5029250
C3-8-4	Solenoid Cover Gasket ~	1 pcs (1 ea)	90-Start up Operation	5079782
MS21044N4	Nut, Self-Locking ~	3 Ea (3 ea)	90-Start up Operation	5061119
MS21083N3	Nut ~	3 Ea (3 ea)	90-Start up Operation	5036469
MS35266-63	Solenoid Cover Screw ~	1 Ea (1 ea)	90-Start up Operation	5038767
MS35338-137	Washer ~	4 Ea (4 ea)	90-Start up Operation	5050160

Job Allocations

Operation	Component Part	Required	Inventory	Allocated
90-Start up Operation	188-FPSS-1032-1/4	2	104	0
	600.1310-AP	1	34	0
	600.1314P	1	60	0
	AN3-14A	1	78	0
	AN4-16A	2	239	0
	AN4-17A	1	163	0
	AN960-10	1	3,363	0
	AN960-10L	4	0	0
	AN960-416	6	0	0
	c2-12-1	2	0	0
	C2-12-7P	2	258	0
	C2-12-8	2	0	0
	C2-13-5	1	0	0
	C2-14-2	4	264	0
	C2-3-1	2	0	0
	C2-3-2-1	2	100	0
	C2-3-3-1	1	29	0
	C2-3-5	2	100	0
	C2-3-8	2	6	0
	C2-4-1	2	0	0
	C2-7-1P	1	119	0
	C2-7-2	2	0	0
	C2-9-3	4	50	0
	C3-10-2	1	0	0
	C3-3-4-1	4	62	0
	C3-3-9	1	0	0
	C3-8-4	1	0	0
	MS21044N4	3	158	0
	MS21083N3	3	87	0
	MS35266-63	1	44	0
	MS35338-137	4	578	0

Part Specifications

Specifications could not be found.

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐	AGAINST DEPARTMENT/PROCESS <table style="width:100%;"> <tr> <td>Skid-tube ☐</td> <td>Cross tube ☐</td> <td>Water Jet ☐</td> <td>Engineering ☐</td> </tr> <tr> <td>Machining ☐</td> <td>Small Fab ☐</td> <td>Prod. Eng. Coord. ☐</td> <td>Quality ☐</td> </tr> <tr> <td>Thermoforming ☐</td> <td>Finishing ☐</td> <td>Rec/Store/Packaging ☐</td> <td>Other ☐</td> </tr> <tr> <td>Large Fab ☐</td> <td>Composite ☐</td> <td>Supplier ☐</td> <td></td> </tr> </table>				Skid-tube ☐	Cross tube ☐	Water Jet ☐	Engineering ☐	Machining ☐	Small Fab ☐	Prod. Eng. Coord. ☐	Quality ☐	Thermoforming ☐	Finishing ☐	Rec/Store/Packaging ☐	Other ☐	Large Fab ☐	Composite ☐	Supplier ☐																																																							
Skid-tube ☐	Cross tube ☐	Water Jet ☐	Engineering ☐																																																																								
Machining ☐	Small Fab ☐	Prod. Eng. Coord. ☐	Quality ☐																																																																								
Thermoforming ☐	Finishing ☐	Rec/Store/Packaging ☐	Other ☐																																																																								
Large Fab ☐	Composite ☐	Supplier ☐																																																																									
Date : _____			MRB (QSI042) Approval																																																																								
DART AEROSPACE Dart Aerospace Ltd. 1270 Aberdeen Street Hawkesbury, ON K6A 1K7 CANADA TEL.: 1 613 632-5200 Email: sales@dartaero.com www.dartaerospace.com Container No: S080096 Part: 648.4701 Job No: 176647 Serial No/Batch: S080096 Revision: 4 Inspector: Exp Date: Instructions: Date: 06/12/18			Completed By																																																																								
			Lead hand / Supervisor Approval Verification																																																																								
			QC / QA Coordinator Approval																																																																								
			Root Cause <table style="width:100%;"> <tr> <td>Environment ☐</td> <td>No Re-verf ☐</td> <td>Cracks ☐</td> <td>Inspection Incomplete/Unqualified ☐</td> <td>wrong Lock Pulled ☐</td> <td>Positioned Wrong ☐</td> </tr> <tr> <td>Design ☐</td> <td>Operator ☐</td> <td>Crimp/Kink/Ripple/Wave ☐</td> <td>Contamination ☐</td> <td>Out of Sequence ☐</td> <td>Outside Dimensions ☐</td> </tr> <tr> <td>Doc/Data ☐</td> <td>Offset/Set ☐</td> <td>Cuffs ☐</td> <td>Countersink ☐</td> <td>Off-set ☐</td> <td>Over/Under tolerance ☐</td> </tr> <tr> <td>Equip/Tooling ☐</td> <td>Supplier ☐</td> <td>Crushing ☐</td> <td>Cut Too Short ☐</td> <td>Mislabeled ☐</td> <td>Part Incorrect ☐</td> </tr> <tr> <td>Handling/Pre ☐</td> <td>Training ☐</td> <td>Heat Treat ☐</td> <td>Instructions Incomplete/Unclear ☐</td> <td>Fit/Function ☐</td> <td>Part Lost/Missing ☐</td> </tr> <tr> <td>Material ☐</td> <td>Use for Testing ☐</td> <td>Wave/Twist in Tube ☐</td> <td>Drill Holes ☐</td> <td>Misaligned/off center ☐</td> <td>Part Moved ☐</td> </tr> <tr> <td>Internal Transport ☐</td> <td>Poor Information ☐</td> <td>Marks/Chatter ☐</td> <td></td> <td></td> <td>Drawing ☐</td> </tr> <tr> <td>Tribal Knowledge ☐</td> <td>Rushing ☐</td> <td></td> <td></td> <td></td> <td>Finish ☐</td> </tr> <tr> <td>LOA ☐</td> <td>Product Improvement ☐</td> <td></td> <td></td> <td></td> <td>Misread ☐</td> </tr> <tr> <td>Substation ☐</td> <td>Process Improvement ☐</td> <td></td> <td></td> <td></td> <td>Turning Sequence ☐</td> </tr> <tr> <td>Past Expiry Date ☐</td> <td>Manufacturing Process ☐</td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>Misidentified ☐</td> <td>Past Due ☐</td> <td></td> <td></td> <td></td> <td></td> </tr> </table>			Environment ☐	No Re-verf ☐	Cracks ☐	Inspection Incomplete/Unqualified ☐	wrong Lock Pulled ☐	Positioned Wrong ☐	Design ☐	Operator ☐	Crimp/Kink/Ripple/Wave ☐	Contamination ☐	Out of Sequence ☐	Outside Dimensions ☐	Doc/Data ☐	Offset/Set ☐	Cuffs ☐	Countersink ☐	Off-set ☐	Over/Under tolerance ☐	Equip/Tooling ☐	Supplier ☐	Crushing ☐	Cut Too Short ☐	Mislabeled ☐	Part Incorrect ☐	Handling/Pre ☐	Training ☐	Heat Treat ☐	Instructions Incomplete/Unclear ☐	Fit/Function ☐	Part Lost/Missing ☐	Material ☐	Use for Testing ☐	Wave/Twist in Tube ☐	Drill Holes ☐	Misaligned/off center ☐	Part Moved ☐	Internal Transport ☐	Poor Information ☐	Marks/Chatter ☐			Drawing ☐	Tribal Knowledge ☐	Rushing ☐				Finish ☐	LOA ☐	Product Improvement ☐				Misread ☐	Substation ☐	Process Improvement ☐				Turning Sequence ☐	Past Expiry Date ☐	Manufacturing Process ☐					Misidentified ☐	Past Due ☐		
Environment ☐	No Re-verf ☐	Cracks ☐	Inspection Incomplete/Unqualified ☐	wrong Lock Pulled ☐	Positioned Wrong ☐																																																																						
Design ☐	Operator ☐	Crimp/Kink/Ripple/Wave ☐	Contamination ☐	Out of Sequence ☐	Outside Dimensions ☐																																																																						
Doc/Data ☐	Offset/Set ☐	Cuffs ☐	Countersink ☐	Off-set ☐	Over/Under tolerance ☐																																																																						
Equip/Tooling ☐	Supplier ☐	Crushing ☐	Cut Too Short ☐	Mislabeled ☐	Part Incorrect ☐																																																																						
Handling/Pre ☐	Training ☐	Heat Treat ☐	Instructions Incomplete/Unclear ☐	Fit/Function ☐	Part Lost/Missing ☐																																																																						
Material ☐	Use for Testing ☐	Wave/Twist in Tube ☐	Drill Holes ☐	Misaligned/off center ☐	Part Moved ☐																																																																						
Internal Transport ☐	Poor Information ☐	Marks/Chatter ☐			Drawing ☐																																																																						
Tribal Knowledge ☐	Rushing ☐				Finish ☐																																																																						
LOA ☐	Product Improvement ☐				Misread ☐																																																																						
Substation ☐	Process Improvement ☐				Turning Sequence ☐																																																																						
Past Expiry Date ☐	Manufacturing Process ☐																																																																										
Misidentified ☐	Past Due ☐																																																																										
OTHER : _____																																																																											